

IN THE DRAWINGS

The Examiner is respectfully requested to approve correction of Figure 1(b) of the drawings, as revised by the drawing amendment dated December 9, 2002, as indicated in red in the attached drawing copy whereby the additional pressure liquid inlet 7' and liquid introduction hole 2' are diametrically transposed in order to correctly illustrate a workable system which is obviously inaccurately portrayed in Figure 1(b) as originally amended.